

General Environmental Incident Summary

Incident: 3996 **Date/Time Notice:** 1/6/2016 **DEM Incident No:**
Responsible Party: BNSF Railway
Date Incident: 1/5/2016 **Time Incident:** 1100 **Duration:** 10 minutes
County: Grand Forks **Twp:** 151 **Rng:** 50 **Sec:** 9 **Qtr:**
Lat: 47.91785 **Long:** -97.04651 **Method:** Interpolation from map
Location Description: BNSF Railroad, 1796 Demers Ave, Car Shop

Submitted By: Matt Richardson **Affiliation:** Contractor
Address: 604 7th Street North
City: Wilton **State:** ND **Zip:** 58579

Received By:

Contact Person: Derek Lampkin
1796 Demers Ave
Grand Forks, ND 58201

Distance Nearest Occupied Building: 300 Feet **Release Contained:** Yes

Type of Incident: Leak from Locomotive Fuel Tank

Description of Released Contaminant: Diesel Fuel

Volume Spilled: 150.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: Unknown **Reported to NRC:** Unknown

Cause of Incident:

Leak was from the sight glass of Locomotive Fuel tank.

Risk Evaluation:

No risks to human health.

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

Potential impacts to the environment are minimal. The spill area was immediately contained, and spilled materials recovered. Wastes have been containerized for disposal. The spill occurred in an area of the yard where stormwater is processed by the on-site oil water separator system.

Action Taken or Planned:

Spill was immediately contained. A contractor was utilized to remove diesel fuel from ground and pavement. Fuel and impacted materials were containerized for off-site disposal.

Wastes Disposal Location: OSI Environmental in Bemidji, MN and Clean Harbors Landfill in Sawyer, ND

Agencies Involved:

Updates

Date: 1/7/2016 ***Status:*** Reviewed - No Action Required

Author: Souder, Taylor

Updated Volume:

Notes:

Contacted responsible party to confirm cleanup. No further action required at this time.